










LATHE LEGS SET-UP DIAGRAM





	4 PIECES
	4 PIECES




CUBIC LEGS SET-UP DIAGRAM







	12 PIECES
	4 PIECES
	4 PIECES


L LEGS SET-UP DIAGRAM











	12 PIECES
	4 PIECES
	4 PIECES









	2 PIECES		4 PIECES		2 PIECES
---	----------	---	----------	---	----------



	4 PIECES		4 PIECES
---	----------	---	----------

			CUBIC LEGS
			PLASTIC LEGS

	SCREW		LATHE LEGS
	L LEGS		LEGS SCREW
	LEGS SCREW		LEGS SCREW